Published regarding engineering changes and improvements

SUBJECT: Discharge Manifolds - 3520, 3527, 3535, 3537 Discharge Manifolds/Valve Plugs - 3521, 3521C, 3531, 3531C, 3541, 3541C

The discharge manifolds for the above models has been enhanced to improve strength and extend life.

On the stainless steel pump models 3521, 3521C, 3531, 3531C, 3541 and 3541C the material of the discharge manifold changes from 316SS to Duplex Stainless Steel. This upgrade to Duplex Stainless Steel provides corrosion resistance. A "D" is stamped on the face of the discharge manifold for identification. The valve plug on the models 3521, 3521C, 3531, 3531C, 3541 and 3541C also changes from 316SS to Duplex Stainless Steel and has a special solid lubricant (CSLT) added for ease in servicing.

These changes start with February 2006 production. All old parts will be replaced with these new parts as inventory is exhausted. All fasteners remain the same. Pump dimensions and port locations remain the same.

	ITEM	OLD PART NUMBER				NEW PART NUMBER			
PUMP MODEL	NO.	Part No.	MTL	Description	QTY	Part No.	MTL	Description	QTY
3521, 3521C 3531, 3531C 3541, 3541C	174	48419	SSNP	Plug, Valve	6	49300	SSD	Plug, Valve	6
3520 3527 3535 3537	185	46394 46335 46394 46335	BBCP NAB BBCP NAB	Manifold, Discharge Manifold, Discharge Manifold, Discharge Manifold, Discharge	1 1 1	49253 49249 76394 76335	BBCP NAB BBCP NAB	Manifold, Discharge Manifold, Discharge Manifold, Discharge Manifold, Discharge	1 1 1
3521, 3521C 3531, 3531C 3541, 3541C	185	46326 46326 48376	SS SS SS	Manifold, Discharge Manifold, Discharge Manifold, Discharge	1 1 1	49299 49299 49302	SSD SSD SSD	Manifold, Discharge Manifold, Discharge Manifold, Discharge	1 1 1
3521 3531 3541	299	814797 814544 816669	SS SS SS	Head, Complete Head, Complete Head, Complete	1 1 1	818373 818372 818371	SS SS SS	Head, Complete Head, Complete Head, Complete	1 1 1

Material Codes:

BBCP=Brass/Chrome Plated NAB=Nickel Aluminum Bronze SS=316SS SSD=Duplex Stainless Steel SSNP=316SS/Nickel Plated

CAT PUMPS
Technical Services Department